



<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill round the outside of a block</b>




<b>Climb milling</b>  G21 G40 G54 G90 T1 M6 S1000 M3  N1 (10MM END MILL) G00 G43 X5. Y10. Z25. Z-10. M8 G01 Y-55. F200. X-105. Y5. X-6. G00 Z25. M5 M30	<b>Conventional milling</b>  G21 G40 G54 G90 T1 M6 S1000 M3  N1 (10MM END MILL) G00 G43 X10. Y5. Z25. Z-10. M8 G01 X-105. F200. Y-55. X5. Y6. G00 Z25. M5 M30
---	---

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Spot / Drill holes</b>




<b>Drilling cycle with dwell</b>  <i>use for centre drilling</i>  <b>G21 G40</b> <b>G54 G90</b> <b>T1 M6</b> <b>S750 M3</b>  <b>N1 (10MM SPOT DRILL)</b> <b>G00 G43 X-10. Y-10. Z25.</b> <b>G82 Z-3. R1. P500 F150. M8</b> <b>X-90.</b> <b>Y-40.</b> <b>X-10.</b> <b>G80</b> <b>M5</b> <b>M30</b>	<b>Standard drilling cycle</b>  <i>use for drill depths of less than 5x drill dia</i>  <b>G21 G40</b> <b>G54 G90</b> <b>T1 M6</b> <b>S750 M3</b>  <b>N1 (10MM JOBBER DRILL)</b> <b>G00 G43 X-10. Y-10. Z25.</b> <b>G81 Z-10. R1. F150. M8</b> <b>X-90.</b> <b>Y-40.</b> <b>X-10.</b> <b>G80</b> <b>M5</b> <b>M30</b>
--	---

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Tap holes</b>




<p><b>Tapping cycle</b></p> <p><i>use for tapping M10x1.5 pitch</i></p> <p><b>G21 G40 G54 G90 T1 M6 S100 M3</b></p> <p><b>N1 (M10*1.5 TAP) G00 G43 X-10. Y-10. Z25. G84 Z-10. R3. F150. M8 X-90. Y-40. X-10. G80 M5 M30</b></p> <p>Feed (F) is calculated as RPM * pitch of thread</p>	<p><b>Tapping cycle</b></p> <p><i>use for tapping M16x2.0 pitch</i></p> <p><b>G21 G40 G54 G90 T1 M6 S100 M3</b></p> <p><b>N1 (M16*2.0 TAP) G00 G43 X-10. Y-10. Z25. G84 Z-10. R3. F200. M8 X-90. Y-40. X-10. G80 M5 M30</b></p>
--	---

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill a bore</b>




<p><i>To mill in a clockwise direction use</i></p> <p><b>G21 G40 G54 G90 T1 M6 S1000 M3</b></p> <p><b>N1 (10MM END MILL) G00 G43 X-50. Y-50. Z25. Z-5. M8 G01 X-10. F200. G02 I-40. G01 X-50. F1000. G00 Z25. M9 M5 M30</b></p>	<p><i>To mill in a anticlockwise direction use</i></p> <p><b>G21 G40 G54 G90 T1 M6 S1000 M3</b></p> <p><b>N1 (10MM END MILL) G00 G43 X-50. Y-50. Z25. Z-5. M8 G01 X-10. F200. G03 I-40. G01 X-50. F1000. G00 Z25. M9 M5 M30</b></p>
---	---

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill round a block with rads on the corners</b>



<p><i>To mill in a clockwise direction use</i></p> <p><b>G21 G40</b>  <b>G54 G90</b>  <b>T1 M6</b>  <b>S1000 M3</b>  <b>N1 (10MM END MILL)</b>  <b>G54 G00 G90 G43 X60. Y0 Z25. H1 S1000 M3</b>  <b>Z-5. M8</b>  <b>G01 X55. F200.</b>  <b>Y-40.</b>  <b>G02 X40. Y-55. R15.</b>  <b>G01 X-40.</b>  <b>G02 X-55. Y-40. R15.</b>  <b>G01 Y40.</b>  <b>G02 X-40. Y55. R15.</b>  <b>G01 X40.</b>  <b>G02 X55. Y40. R15.</b>  <b>G01 Y0</b>  <b>X60.</b>  <b>G00 Z25. M5</b>  <b>M30</b></p>	<p><i>To mill in a anticlockwise direction use</i></p> <p><b>G21 G40</b>  <b>G54 G90</b>  <b>T1 M6</b>  <b>S1000 M3</b>  <b>N1 (10MM END MILL)</b>  <b>G00 G43 X60. Y0 Z25.</b>  <b>Z-5. M8</b>  <b>G01 X55. F200.</b>  <b>Y40.</b>  <b>G03 X40. Y55. R15.</b>  <b>G01 X-40.</b>  <b>G03 X-55. Y40. R15.</b>  <b>G01 Y-40.</b>  <b>G03 X-40. Y-55. R15.</b>  <b>G01 X40.</b>  <b>G03 X55. Y-40. R15.</b>  <b>G01 Y0</b>  <b>X60.</b>  <b>G00 Z25. M5</b>  <b>M30</b></p>
--	--

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill outside a block using cutter compensation</b>




*To mill in a clockwise direction use*

G21 G40  
G54 G90  
T1 M6  
S1000 M3  
N1 (10MM END MILL)  
G00 G43 X60. Y0 Z25. D30  
Z-5. M8  
G01 G41 X50. F200.  
Y-40.  
G02 X40. Y-50. R10.  
G01 X-40.  
G02 X-50. Y-40. R10.  
G01 Y40.  
G02 X-40. Y50. R10.  
G01 X40.  
G02 X50. Y40. R10.  
G01 Y0  
G40 X60.  
G00 Z25. M5  
M30

*To mill in a anticlockwise direction use*


G21 G40  
G54 G90  
T1 M6  
S1000 M3  
N1 (10MM END MILL)  
G00 G43 X60. Y0 Z25. D30  
Z-5. M8  
G01 G42 X50. F200.  
Y40.  
G03 X40. Y50. R10.  
G01 X-40.  
G03 X-50. Y40. R10.  
G01 Y-40.  
G03 X-40. Y-50. R10.  
G01 X40.  
G03 X50. Y-40. R10.  
G01 Y0  
G40 X60.  
G00 Z25. M5  
M30

<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill inside a block using cutter compensation</b>



<p><i>To mill in a clockwise direction use</i></p> <p>G21 G40  G54 G90  T1 M6  S1000 M3  N1 (10MM END MILL)  G00 G43 X40. Y0 Z25. D30  Z-5. M8  G01 G42 X50. F200.  Y-40.  G02 X40. Y-50. R10.  G01 X-40.  G02 X-50. Y-40. R10.  G01 Y40.  G02 X-40. Y50. R10.  G01 X40.  G02 X50. Y40. R10.  G01 Y0  G40 X40.  G00 Z25. M5  M30</p>	<p><i>To mill in a anticlockwise direction use</i></p> <p>G21 G40  G54 G90  T1 M6  S1000 M3  N1 (10MM END MILL)  G00 G43 X40. Y0 Z25. D30  Z-5. M8  G01 G41 X50. F200.  Y40.  G03 X40. Y50. R10.  G01 X-40.  G03 X-50. Y40. R10.  G01 Y-40.  G03 X-40. Y-50. R10.  G01 X40.  G03 X50. Y-40. R10.  G01 Y0  G40 X40.  G00 Z25. M5  M30</p>
--	--


<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Mill a 30° arc using compensation</b>



<p><i>To mill in a clockwise direction use</i></p> <p><b>G21 G40 G54 G90 T1 M6 S1000 M3</b></p> <p><b>N1 (10MM END MILL) G00 G43 X45.36. Y45.36 Z25. D30 Z-5. M8 G01 G42 X35.36 Y35.36. F200. G02 X50. Y0 R50. G01 Y-6. G00 Z25. G40 M5 M30</b></p>	<p><i>To mill in a anticlockwise direction use</i></p> <p><b>G21 G40 G54 G90 T1 M6 S1000 M3</b></p> <p><b>N1 (10MM END MILL) G00 G43 X60. Y-6. Z25. D30 Z-5. M8 G01 G41 X50. F200. Y0 G03 X35.36 Y35.36 R50. G00 Z25. G40 M5 M30</b></p>
---	--



<b>Autovalues Engineering</b>	<b>NC Code, Milling Using Mach3</b>
<b>How do I :-</b>	<b>Work out angles using SIN and COS</b>



*To find dimension 'A'*

$$A = \text{COS}(30) * \text{Rad}$$

$$\text{Rad} = 50.00$$

$$\text{COS}(30) = .866$$

$$A = 50.00 * .866$$

$$A = 43.30$$

*To find dimension 'B'*

$$B = \text{SIN}(30) * \text{Rad}$$

$$\text{Rad} = 50.00$$

$$\text{SIN}(30) = .5$$

$$B = 50.00 * .5$$

$$B = 25.00$$

*To find dimension 'C'*

$$C = \text{COS}(45) * \text{Rad}$$

$$\text{Rad} = 50.00$$

$$\text{COS}(45) = .7071$$

$$C = 50.00 * .7071$$

$$C = 35.36$$

*To find dimension 'D'*

$$D = \text{SIN}(45) * \text{Rad}$$

$$\text{Rad} = 50.00$$

$$\text{SIN}(45) = .7071$$

$$D = 50.00 * .7071$$

$$D = 35.36$$