


1 2 3 4 5 6 7 8 9 10 11 12 13 14



1 MPa = 10 Bar

Modifications			Title		Page: 9/9
Date	Draw	Name	Machine M4 - Pneumatic		01-01-50-110
	Check	Guiot			
	Norm	MG/JK			
Filename: p:\precimill\zeichnungen\elektrisch\maschine m4.spl			Drawing Nr.:		

# Connection of parts DCS Precimill M4

*Italic = cable number, Bold = connector number*

G1 (old)

16				
<b>31</b>	<b>32</b>	<b>33</b>	<b>34</b>	<b>35</b>
89	90	64	15	
<b>11</b>	<b>12</b>	<b>13</b>	<b>14</b>	<b>15</b>
21	22	23	24	25
66	67	68	69	
<b>41</b>	<b>42</b>	<b>43</b>	<b>44</b>	<b>45</b>
	63	6		

K4 (old)

37			12
<b>A1</b>			<b>A2</b>
11	12		
<b>1</b>	<b>3</b>	<b>5</b>	<b>21</b>
2	4	6	22
1	9		
			<b>A2</b>
			12

K4 (new)

11	12	
<b>1</b>	<b>3</b>	<b>5</b>
		37
<b>13</b>	<b>21</b>	<b>A1</b>
<b>14</b>	<b>22</b>	<b>A2</b>
		12
<b>2</b>	<b>4</b>	<b>6</b>
1	9	

K3 (old)

71	30	51	40	48
<b>13</b>	<b>23</b>	<b>33</b>	<b>41</b>	<b>S3</b>
<b>14</b>	<b>24</b>	<b>34</b>	<b>42</b>	<b>S4</b>
41	31		28	6

YPOW

HF-Spindle

	8	9	
7			2
		1	
6			3
	5	4	

- 1** Phase U
- 2** Phase V
- 3** Phase W
- 4** Signal GND
- 5** Number of Poles (not used)
- 6** Hall Switch (6p/rotation) (n.u)
- 7** Speed Limitation (n.u)
- 8** PTC Resistor
- 9** Case Ground

YPOW Yellow Piece'o Wire

## K3 (new)

5	28	48	DO-1
A1	S33		
S34	S11		
DO-2		6	
S12	51	52	A2
Power			
K1			
K2			
43	44	13	14
5	40	71	41
33	34	23	24
51	YPOW	30	31

## K1 (new)

57	58	52
1	3	5
55		5
13	21	A1
14	22	A2
4		6
2	4	6
8	10	63

## G1 (new)


	90	89
	4	5 6
	16	15 64
	1	2 3
	24VDC	
	○ 1	
	○ 2	
	○ 3	
	○ 4	
	7	8 9
	66	67 68
	10	11 12
	69	63 6

DO-1 Door switch contact 1 (white)


DO-2 Door switch contact 2 (blue)

YPOW Yellow Piece'o Wire

## Connections G1 (24V-Powersupply) M3 / M4 System



## Adjusting the Spindle speed



First check the tension without running the spindle. Then check and readjust the tension with running spindle.

V

SFU Typ: 21.49 (1V = 6'000 RPM) ( start/stop 1s ≈ 6'000 RPM)

G1-Poti Nr.	Tension (VDC)	G1-old / new	Ca. rpm
1	2.15 (2.37)	12 - 21 / 4 - 7	~12'900
2	4.30 (4.65)	12 - 22 / 4 - 8	~25'800
3	6.45 (6.84)	12 - 23 / 4 - 9	~38'700
4 ↓	8.60 (8.85)	12 - 24 / 4 - 10	~51'600
4	7.50 (7.80)	12 - 24 / 4 - 10	~45'000

SFU Typ: 21.46 (1V = 10'000 RPM) ( start/stop 1s ≈ 10'000 RPM)

G1-Poti Nr.	Tension (VDC)	G1-old / new	Ca. rpm
1	1.29	12 - 21 / 4 - 7	~12'900
2	2.58	12 - 22 / 4 - 8	~25'800
3	3.87	12 - 23 / 4 - 9	~38'700
4	5.16	12 - 24 / 4 - 10	~51'600
4	4.50	12 - 24 / 4 - 10	~45'000

# Machine In- and Outputs

Press Key combination „ALT“ + „SCROLL“ (rollen) + 0-9 or A-F to call the function in DF\_Fraes.  
In some cases the Key „E“ will not be accepted. In this case Type „N“.

Output Bit No.	Function M3 Machine	Function M4 Machine	DB37 Pin
0	Coolant pump	Coolant pump	25
1	Spindle run (RSR)	Spindle run (RSR)	33
2	Automatic OFF	Automatic OFF	26
3	Machine ON	Machine ON	34
4	Automatic call	Automatic call ✓	27
5	Speed 1	Speed 1	35
6	Speed 2	Speed 2	28
7	Speed 3	Speed 3	36
8	Speed 4	Speed 4	21
9			29
A	ATC back	Flipper switches override !	22
B	ATC for	Flipper unlock ✓ !	30
C	ATC rotate	ATC rotate	23
D	Tool unclamp	Tool unclamp	31
E	Face A	Face A	24
F	Face B	Face B ✓	32
-	0V	0V	20
Input Bit No.			DB37 Pin
0	X+ L.S.	X+ L.S.	3
1	Y+ L.S.	Y+ L.S.	4
2	Z+ L.S.	Z+ L.S.	5
3	X- L.S.	X- L.S.	6
4	Y- L.S.	Y- L.S.	7
5	Z- L.S.	Z- L.S.	8
6	EMG stop	EMG stop	9
7	Flipper FB	Flipper FB	10
8	(Reset enable X)	(Reset enable X)	-
9	(Reset enable Y)	(Reset enable Y)	-
A	(Reset enable Z)	(Reset enable Z)	-
B	X Ref. L.S.	X Ref. L.S.	13
C	Y Ref. L.S.	Y Ref. L.S.	12
D	Z Ref. L.S.	Z Ref. L.S.	11
E	ATC FB	ATC FB	1
F	Tool length	Tool length	2
-	„+Vcc“	„+Vcc“	14

no lemad  
sine lilt.  
nisan  
laddimie  
asud.

C:\DF\_FRAES > nt.

flipper position.

testimney

C:\PP\_FRAES > flip - tat

## Wenderplatine M4

vom Schrank	rot	0	1	6 0	Rot	WW Motor
vom Schrank	grün	0	2	5 0	Schwarz	WW Motor
WW Ini	Schwarz	0	3	4 0	Gelb	Schrank
WW Ini	Blau	0	4 X1	3 0	Grün	Schrank
WW Ini	Braun	0	5	2 0	Schwarz	Wendermotor
Messsensor	Schwarz	0	6	1 0	Rot	Wendermotor
Messsensor	Blau	0	7			
Messsensor	Braun	0	8			

Flipper Add-On	Schwarz	X4 /2
	Rot	X4 /3
	Blau	Ini Oben
	Braun	Ini Oben
	Schwarz	Ini Oben
	Blau	Ini Unten
	Braun	Ini Unten
	Schwarz	Ini Unten

vom Schrank	Blau	0	1	8 0	Weiss	Schrank
2 FbHr	Schwarz	0	2	7 0	Blau	Add-On
2 FbHr	Rot	0	3	6 0		
2 FbHr	Grün	0	4 X2	5 0	Schwarz	Schrank
2 FbHr	Gelb	0	5	4 0	Weiss	Schrank
2 FbHr	Blau	0	6	3 0	Rot	Add-On
vom Schrank	Grau	0	7	2 0	Schwarz	Add-On
vom Schrank	Lila	0	8	1 0	Braun	Schrank

SFF Add-On

0  
0  
0  
0  
0  
0  
0  
0

V1 Schwarz	0	1	2	3	4	5	6	7	8
V1 Rot	0	0	0	0	0	0	0	0	0
Schrank Gelb	0	0	0	0	0	0	0	0	0
Schrank und Add-On Braun	0	0	0	0	0	0	0	0	0
V2 Schwarz	0	0	0	0	0	0	0	0	0
V2 Rot	0	0	0	0	0	0	0	0	0
V4 Schwarz	0	0	0	0	0	0	0	0	0
V4 Rot	0	0	0	0	0	0	0	0	0