



Mach3 Breakout Board w/ Relay & PWM



Mach3 Typical VFD Setup

Automation Technology Inc.




Programming Notes:

PD001 = 1 (Source of operation commands)

PD002 = 1 (Source of operating frequency)


Typical Limit Switch Setup

Automation Technology Inc.



Typical Axis Setup

Automation Technology Inc.



Complete support for Mach3.

Can power the board using either the USB port or an external 5v.

All Input signals are opto-isolated, which prevents highvoltages from affecting the rest of the breakout board.

P1 (Pin 1) can be used to output the PWM signal and control the spindle speed. The input is opto-isolated.

All LPT port names and pin numbers are printed on board and can be easily read.

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Port #1
☒ Port Enabled
0x378 Port Address
Entry in Hex 0-9 A-F only

Port #2
☐ Port Enabled
0x278 Port Address
Entry in Hex 0-9 A-F only
☐ Pins 2-9 as inputs

OR

MaxNC Mode
☐ Max CL Mode enabled
☐ Max NC-10 Wave Drive
Program restart necessary

Restart if changed
☐ Sherline 1/2 Pulse mode.
☐ ModBus InputOutput Support
☐ ModBus PlugIn Supported.
☐ TCP Modbus support
☐ Event Driven Serial Control

Kernel Speed
☐ 25000Hz ☐ 35000Hz ☐ 45000Hz ☒ 60000hz
☐ 65000hz ☐ 75000hz ☐ 100khz
Note: Software must be restarted and motors retuned if kernel speed is changed.

OK Cancel Apply

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Step Pin#	Dir Pin#	Dir LowActi...	Step Low A...	Step Port	Dir Port
X Axis		2	3			1	1
Y Axis		4	5			1	1
Z Axis		6	7			1	1
A Axis		8	9			1	1
B Axis		0	0			0	0
C Axis		0	0			0	0
Spindle		1	0			1	1




























OK Cancel Apply

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low	Emulated	HotKey
X --		1	0			0
X Home		1	11			0
Y ++		1	0			0
Y --		1	0			0
Y Home		1	12			0
Z ++		1	0			0
Z --		1	0			0
Z Home		1	13			0
A ++		1	0			0

Pins 10-13 and 15 are inputs. Only these 5 pin numbers may be used on this screen

Automated Setup of Inputs




























OK Cancel Apply

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low	Emulated	HotKey
Input #4		1	0			0
Probe		1	0			0
Index		1	0			0
Limit Ovrld		1	0			0
EStop		1	10			0
THC On		1	0			0
THC Up		1	0			0
THC Down		1	0			0
OEM Trig #1		1	0			0

Pins 10-13 and 15 are inputs. Only these 5 pin numbers may be used on this screen

Automated Setup of Inputs

OK Cancel Apply

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low
Output #1		1	17	
Output #2		1	0	
Output #3		1	0	
Output #4		1	0	
Output #5		1	0	
Output #6		1	0	
Charge Pump		1	0	
Charge Pump2		1	0	
Current Hi/Low		1	0	
Output #7		1	0	

Pins 2 - 9 , 1, 14, 16, and 17 are output pins. No other pin numbers should be used.

OK Cancel Apply

Project Notes

Automation Technology Inc.

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Relay Control

☐ Disable Spindle Relays

Clockwise (M3) Output #

CCW (M4) Output #

Output Signal #'s 1-6

Flood Mist Control

☐ Disable Flood/Mist relays Delay

Mist M7 Output #

Flood M8 Output #

Output Signal #'s 1-6

ModBus Spindle - Use Step/Dir as well

☐ Enabled Reg 64 - 127

Max ADC Count

Motor Control

☒ Use Spindle Motor Output

☒ PWM Control

☐ Step/Dir Motor

PWMBase Freq.

Minimum PWM %

General Parameters

CW Delay Spin UP Seconds

CCW Delay Spin UP Seconds

CW Delay Spind DOWN Seconds

CCW Delay Spin DOWN Seconds

☐ Immediate Relay off before delay

Special Functions

☐ Use Spindle Feedback in Sync Modes

☐ Closed Loop Spindle Control

P I D

☐ Spindle Speed Averaging

Special Options, Usually Off

☐ HotWire Heat for Jog

☐ Laser Mode. freq I

☐ Torch Volts Control

☐ Torch Auto Off

OK Cancel Apply

Project Notes

Automation Technology Inc.