

```

1  function m6()
2
3      local inst = mc.mcGetInstance('M6 macro') -- This will allow logging the API calls
        with caller information.
4
5          --Start tool change
6          mc.mcCntlGcodeExecuteWait(inst, "G90 G53 G0 Z0.0");--Move the Z axis to
            Reference 0.
7
8          locateSpindle, rc = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT6) --Turn ON
            spindle lock.
9          rc = mc.mcSignalSetState(locateSpindle, 1) --Spindle lock ON
10         currentRPM, rc = mc.mcSpindleGetCommandRPM(inst) -- save the current RPM to
            restore later.
11         rc = mc.mcSpindleSetCommandRPM(inst, 15) -- use instead of execute M3 S15
12         --The possible values to use with the mc.mcSpindleSetDirectionWait() below
13         --mc.MC_SPINDLE_OFF
14         --mc.MC_SPINDLE_FWD
15         --mc.MC_SPINDLE_REV
16         rc = mc.mcSpindleSetDirectionWait(inst, mc.MC_SPINDLE_FWD)
17         -- There is no input that tells when the keylock has engaged or disengaged.
18         wx.wxSleep (5) --Wait 5 seconds for slow rotation to orient spindle in keylock.
19         rc = mc.mcSpindleSetDirectionWait(inst, mc.MC_SPINDLE_OFF) --Turn OFF spindle.
20         wx.wxSleep (1) --Wait 1 second
21
22         --Carousel pushed OUT to cradle tool oriented in spindle.
23         CarouselOut = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT5) --Output 5 with 24V
            relay is used to push carousel out.
24         mc.mcSignalSetState (CarouselOut, 1) --Carousel OUT motor ON
25
26         -- Use 24V PNP switch (INPUT 5) to stop motor for carousel out.
27         local hSig, state
28         hSig, rc = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT5)
29         state, rc = mc.mcSignalGetState(hSig, mc.OSIG_OUTPUT5)
30         if (state == 1) then
31             rc = mc.mcSignalWait(inst, mc.ISIG_INPUT5, mc.WAIT_MODE_HIGH, 10) -- Wait
                on input 5 to go HIGH 10 seconds.
32
33         -- Always put a timeout in you want to be able to catch errors instead of
            waiting indefinitely.
34         -- If you want to wait on the input to go high, use mc.WAIT_MODE_HIGH. Case is
            important!!!
35         -- you really want to check the return code from EVERY API call for
            success/failure.
36         -- Below will abort the script gracefully if there is an error.
37     end
38     if (rc ~= mc.MERROR_NOERROR) then
39         wx.wxMessageBox ("Timed out waiting for INPUT 5 to go high.")
40         --mc.mcCntlAlarm (inst, 100, "Timed out waiting for input 5 to go high.")
41         --return(100) -- 100 here and above is just some number I dreamed up. you
            could plan your own error number scheme.
42     end
43     mc.mcSignalSetState(CarouselOut, 0) --Carousel OUT motor OFF
44     wx.wxSleep (1) --Wait 1 second
45
46     --Release tool from spindle
47     releaseSpindle = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT7) --Turn ON air to
            release tool from spindle
48     mc.mcSignalSetState (releaseSpindle, 1) --Air ON
49     wx.wxSleep (1) --Wait 1 second
50
51     --Move Z axis up 4 inches to clear tool in spindle
52     mc.mcCntlGcodeExecuteWait(inst, "G90 G53 G0 Z4.0");--Move the Z axis up 4"
53     wx.wxMessageBox ("CHANGE TOOL THEN CLICK OK TO CONTINUE")
54
55     --Move Z axis down 4 inches engage tool
56     mc.mcCntlGcodeExecuteWait(inst, "G90 G53 G0 Z0.0");--Move the Z axis down 4" to
            Reference 0.
57     wx.wxSleep (1) --Wait 1 second

```

```

58
59      --Engage tool in spindle
60      releaseSpindle = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT7) --Turn OFF air to
grab tool in spindle
61      mc.mcSignalSetState (releaseSpindle, 0) --Air OFF
62      wx.wxSleep (1) --Wait 1 second
63      locateSpindle = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT6) --Spindle lock OFF
64      mc.mcSignalSetState (locateSpindle, 0) --Turn OFF spindle lock
65      wx.wxSleep (1)
66
67      --Carousel retracted to clear tool
68      CarouselRetract = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT4) --Pull carousel
IN to disengage tool
69      mc.mcSignalSetState (CarouselRetract, 1) --Carosel IN motor ON
70
71      -- Use 24V PNP switch (INPUT 4) to stop motor for carousel in.
72
73      hSig, rc = mc.mcSignalGetHandle (inst, mc.OSIG_OUTPUT4)
74      state, rc = mc.mcSignalGetState(hSig, mc.OSIG_OUTPUT4)
75      if (state == 1) then
76          rc = mc.mcSignalWait(inst, mc.ISIG_INPUT4, mc.WAIT_MODE_HIGH, 10) -- Wait
on input 4 to go HIGH 10 seconds.
77      end
78
79      if (rc ~= mc.MERROR_NOERROR) then
80          wx.wxMessageBox ("Timed out waiting for INPUT 4 to go high.")
81          --mc.mcCntlAlarm (inst, 100, "Timed out waiting for input 4 to go high.")
82          --return(100) -- 100 here and above is just some number I dreamed up. you
could plan your own error number scheme.
83      end
84      mc.mcSignalSetState(CarouselRetract, 0)
85      --wx.wxSleep (1)
86      end
87
88      if (mc.mcInEditor() == 1) then
89          m6()
90      end

```