

Engine Configuration... Ports & Pins

Port Setup and Axis Selection

Motor Outputs

Input Signals

Output Signals

Encoder/MPG's

Spindle Setup

Mill Options

Signal	Enabled	Step Pin#	Dir Pin#	Dir LowActive	Step Low Ac...	Step Port	Dir Port
X Axis		1	7			1	1
Y Axis		8	3			1	1
Z Axis		5	4			1	1
A Axis		8	3			1	1
B Axis		0	0			0	0
C Axis		0	0			0	0
Spindle		0	0			0	0

OK

Cancel

Apply