

Engine Configuration... Ports & Pins

Port Setup and Axis Selection

Motor Outputs























Input Signals

Output Signals

Encoder/MPG's

Spindle Setup

Mill Options

Signal	Enabled	Port #	Pin Number	Active Low
Digit Trig		1	0	
Enable1		1	14	
Enable2		1	2	
Enable3		1	6	
Enable4		1	2	
Enable5		1	0	
Enable6		1	0	
Output #1		1	9	
Output #2		1	0	
Output #3		1	0	
Output #4		1	0	

Pins 2 - 9 , 1, 14, 16, and 17 are output pins. No other pin numbers should be used.

OK

Cancel

Apply