

Mach3 CNC Controller

Config Function Cfg's View Wizards Operator PlugIn Control Help

Program Run Alt+1

MDI Alt+2

ToolPath Alt+4

Offsets Alt+5

Settings Alt+6

Diagnostics Alt+7

M3->G15 G1 G17

alien head profile)
(File created: Monday, February 25, 2019 - 01:14 PM)
(for Mach2/3 from Vectric)
(Material Size)
(X= 135.000, Y= 160.000, Z= 19.000)
()
(Toolpaths used in this file:)
(Profile 1)
(Contour 1)

REF
ALL
HOMEZero
X

-56.823

Zero
Y

+145.666

Zero
Z

-79.860

Zero
4

+0.0000

OFFLINE

GOTO
ZERO

To Go

Machine
Coord's

File: E:\alien head profile.b1

Load Wizards

NFS Wizards

Cycle Start
<Alt-R>

Edit G-Code

Rewind Ctrl+W

Feed Hold
<Spc>

Recent File

Single BLK Alt+N

Stop
<Alt-S>

Close G-Code

Reverse Run

Load G-Code

Block Delete

Set Next Line

M1 Optional Stop

Line 0

Flood Ctrl+F

Run From Here

Dwell

CV Mode

Reset

G-Codes

M-Codes

Safe Z
On Off
Z Inhibit
+0.000

Tool Information

Tool

0

Change
Tool

Dia.

+0.0000

H

+0.0000

Toolchange Pos.

Auto Test Zero

Remember

Return

Elapsed

00:01

Jog ON OFF Ctrl+Alt+J

Feed

Rapid

FRO

100

FRO

Feed

Units/Min

Units/Rev

History

Clear

Status:

Profile 2

Profile: Mach3