



Just as an example, using the groove tool.



This is was rough profile with small clear and small depth per pass.



Changing the rough profile inputs.

