



ALARM Signal wiring optional
Requires inputs to be
configured correctly



CNC-038

2/05/2013 4:17:03 PM

Sheet: 1/1