

# Output - Mach3

- Enable — Port 0, Pin 0
- Spindle — Port 0, Pin 1
- Cooling — Port 0, Pin 2
- Reserve — Port 0, Pin 3

