



Model	GDL80-20-30Z/2.2
Voltage	220 V
Power	2.2 kw
Current	7.6 A
Frequency	1000 Hz
Rotating speed	30000 rpm
Pole number	4P
Phase number	3
Rotating direction	Rotate anticlockwise from the shaft extension end
Tool holder	ISO20 (Parfaite is recommended)
Blind rivet	ISO20-15° (Parfaite is recommended)
Weight	8 KG

Special warning:

1. The electric main shaft shall be installed at the clamped position; otherwise the bearing will be easily damaged!
2. The main shaft shall entirely stop before the tool changing. The manual tool changing button shall not act during the rotation of the shaft; otherwise it will easily result in the seizure of the shaft!
3. The compressed air shall be clean and dry, and the filter accuracy shall be 0.1micron! Air seal is normally open. It is recommended to use the two-level filter, and the filter accuracy is 0.5 micron/ 0.1 micron respectively. The air filter is installed with the self-discharge device.

										Outline diagram	
Marks	Number of places	Zoning	Modified document number	Signature	Date						
Designed by			Standardized by			Phase mark		Weight	Scale	GDL80-20-30Z/2.2	
Reviewed by											
Processed by			Approved by			Total page(s)		Page			