

NOTE! ALL PIN NUMBERS ARE DEVICE PIN NUMBERS, NOT CABLE CONDUCTOR NUMBERS.

RPM INPUT FROM
SERVO SPINDLE
ENCODER INDEX PULSE:
PULSE IS TOO SHORT
FOR DIRECT USE, LESS
THAN 1µs AT HIGH
SPEEDS, SO NEEDS TO
BE STRETCHED.
SSS NEEDS TO BE
CMOS VERSION FOR
TTL COMPATIBILITY.

